

PUBLIC SAFETY ALERT: Hoistway door safety retainers have been required by ASME A17.1 since the 1992 addenda. If a hoistway door is missing this retainer, it is considered a serious safety concern and immediate corrective action should be taken. You may contact this office if further assistance is required. See rule 875-72.1(3)(a)(1) and (2)